

40th

TURBOMACHINERY SYMPOSIUM

CASE STUDY

‘BALANCE INSTABILITY AND VIBRATION ON A 6 MW INDUCTION MOTOR ROTOR’

Authors

Gunnar Porsby (ABB, Sweden)

Sameer S. Patwardhan (Bechtel OG&C Corp., Houston, Texas)

Siddharth (Sid) Shinde (Chevron, Houston, Texas)

Barry Wood (Chevron, Richmond, California)

Induction Motor at Test Stand



Stabilizer Overhead Compressor


- Centrifugal compressor (with 'side stream')
- Two stage compression used for mixing vapor/gas from 'stabilizer' column into feed gas stream
- Speed increasing gearbox
- 6 MW induction motor driver with variable frequency drive
- Large variation in inlet flow
- Complicated control system
- No spare compressor

Induction Motor Driver

- 6 MW induction motor
- 6.6 kV 3 Ph 60 Hz
- Coupled with variable frequency drive (VFD)
- Motor designed per API 541 and IEC (hybrid standard)
- Routine and complete run tests including heat run test, unbalance response test, mechanical run test, over-speed test etc.

Motor Design: Squirrel Cage Induction Rotor


Rotor core
(Laminated steel)



Spider shaft
(Homogenous forged steel)



Squirrel cage
(Copper)



Rotor assembly AND




Complete rotor

The sheet laminations are shrunk on to the rotor shaft and compressed in axial direction




Unbalance weights

Motor Design: Sleeve Bearings and Stiffness Chain




Sleeve bearings with oil film for damping and stiffness




Stiff shaft design with unbalance force pathway

Separation Margin and Balancing




Normally 4 pole motors are run below first critical speed with sufficient separation margin (sub-critical operation)




2-plane balancing at reduced speed is often sufficient for sub-critical operation

API 541 Vibration Requirement



Shaft vibration limits
(Relative bearing housing using non-contact probes)




Bearing housing vibration limits
(Using bearing-mounted velocimeters)

Factory Acceptance Test (FAT)

- High vibration levels during over-speed test
- Vibrations above normal for the machine type at running speed (1800 rpm)
- High vibrations during over-speed test led to bearing failure




Factory Acceptance Test Results



Bearing Vibrations during
Overspeed Test

Failed NDE Bearing during 4
hour Mechanical Run Test




Investigation After FAT

- Assumption:
 - The vibrations are caused by unbalance in the rotor due to initial settlement during the first heat run and/or over speed test
- Decisions
 - Residual Unbalance Check → Re-Balance at Low Speed (1000 rpm) → New Test
- Result
 - Vibrations still not meeting the requirements

FAT Results After Re-Balancing

| | FAT | | After Re-balancing | | |
|-----------------|----------------------------|-----------------------------|----------------------------|-----------------------------|---|
| Balancing plane | Residual unbalance [kg mm] | Residual unbalance mass [g] | Residual unbalance [kg mm] | Residual unbalance mass [g] | API 541 requirement residual unbalance mass [g] |
| DE | 33 | 117 | 2 | 6.2 | 7.8 |
| NDE | 47 | 169 | 1 | 2.1 | 7.8 |

Residual Un-Balance After Re-Balancing



Bearing Vibration Results After Re-Balancing


More Investigations...

- Assumptions:
 - Other effects than only settling.
- Decisions:
 - Check balancing state again, this time at different speeds
- Findings
 - The balancing state at 1000 rpm had changed again
 - Balancing state was also changing with speed
- Conclusions
 - Unbalance of the rotor was not caused by only settlings in the rotor


| | NDE | | DE | |
|----------------|----------------------------------|-----------------------------------|----------------------------------|-----------------------------------|
| Speed [rpm] | Residual unbalance [kg mm] | Residual unbalance mass [g] | Residual unbalance [kg mm] | Residual unbalance mass [g] |
| 249 | 7.4 | 26.3 | 18.8 | 67.1 |
| 500 | 3.8 | 13.7 | 20.2 | 72 |
| 751 | 1.9 | 6.7 | 23.2 | 82.7 |

A Theory Was Formulated...


- Measurements showed that individual sheets in the lamination were skewed/buckled
- Centrifugal force acts to 'straighten' the sheet metal plates which could lead to changed balancing state



Rotor core measurements



Sheet metal plate
at 'high' speed




Corrective Actions

- Attempt to recompress the rotor core lamination to make it perpendicular to the rotor centre line
- Result:
 - Improved vibration but still not meeting requirement, balancing state still changes with speed
- Conclusion:
 - Recompression not working due to high friction between rotor core and spider shaft

After recompression:

Rotor Core Compression




'Pull-rods'

| | NDE | | DE | |
|-------------|----------------------------|-----------------------------|----------------------------|-----------------------------|
| Speed [rpm] | Residual unbalance [kg mm] | Residual unbalance mass [g] | Residual unbalance [kg mm] | Residual unbalance mass [g] |
| 249 | 20.2 | 72.1 | 17.1 | 61.2 |
| 500 | 19.7 | 70.5 | 20.1 | 71.7 |
| 750 | 17.4 | 62.1 | 22.3 | 79.8 |
| 1000 | 14.4 | 51.3 | 25.1 | 89.7 |


| Balancing @ 1000 rpm | | | |
|----------------------|----------------------------|-----------------------------|---|
| Balancing plane | Residual unbalance [kg mm] | Residual unbalance mass [g] | API 541 requirement residual unbalance mass [g] |
| DE | 1 | 4.8 | 7.8 |
| NDE | 2 | 7.6 | 7.8 |

Test After Operating Speed Balancing

- Solution for the problem:
 - Balancing of rotor at full speed (settling effects within balancing)
- Results
 - After full speed balancing vibration levels are within required limits
- Forced unbalance tests for final verification



NDE X-direction



NDE Y-direction


FAT: Residual Unbalance Test Per API 541

- The residual unbalance in the rotor was found to be above maximum allowable residual unbalance
- It was now decided that a new rotor should be manufactured

| | DE | NDE | Comment |
|--|-------|------|---|
| Journal Static Load [kg] | 2410 | 2010 | |
| Max Continuous Speed [rpm] | 1800 | 1800 | 1300 rpm is used as Nmc in the protocol |
| Radius Correction Flange [mm] | 280 | 280 | |
| Max allowable res. Unbalance [gmm] | 8502 | 7091 | |
| Calculated res. unbalance in rotor [gmm] | 10747 | 7250 | |

Root Cause Analysis Findings

Problem:



Analysis:

Insufficient compression of rotor core due to malfunction in the cooling process of rotor core during manufacturing process

Resolution:

Manufacturing of new rotor with changed manufacturing process for the core shrinking

Resolution: Manufacture New Rotor

- New process for shrinking the core onto the shaft:
 - Cooling from the top down to get axial pressure on the entire length of the rotor core


Rotor core cooling



Fans to cool 'Top Part' of rotor core

'Insulation' around bottom part of rotor core

New Rotor: Residual Unbalance & Vibration Tests



Old rotor

New rotor

CONCLUSION

- It is very difficult to correct a rotor after a distorted cooling or skewed lamination fit on the rotor core
- Trial and error attempts to diagnose and repair this type of rotor problem can be very time consuming and without guarantee of success.
- In a schedule oriented environment, it is important to have all the necessary resources involved to quickly determine if the problem can be corrected and a quality machine assured. Sometimes it may be necessary to move in parallel in attempting to repair the rotor and preparing to manufacture a new rotor.